


## IMAGE TRAIN FOR QSI500

### Adapters required for the CDK17 and CDK20




QSI500 WSG Body		8.81 remaining BF
3.5" Focuser (racked in)	3	5.81
<b>Focus position (0 to 1.3")</b>	<b>0.51</b>	5.3
3.5" to SecureFit, 2.1" - 200361-2	2.1	3.2
SecureFit 1/2" Spacer - 200377	0	3.2
CCD Adapter - 200397	0.25	2.95
CCD Adapter for QSI WSG - 600331	0.8	2.15
QSI500, WSG Body with no cover	1.75	0.4

### Adapters required for the CDK12.5

Distance to Focuser Mounting Surface

10.45



QSI500 WSG Body		10.45 remaining BF
3.5" Focuser (racked in)	3.25	7.2
<b>Focus position (0 to 1.3")</b>	<b>0.4</b>	6.8
2.75" to SecureFit, 2.1" - 125357-2	3.5	3.3
SecureFit 1/2" Spacer - 200377	0.5	2.8
SecureFit 1/2" Spacer - 200397	0.25	2.55
CCD Adapter for STQSI - 600331	0.8	1.75
QSI500, WSG Body with no cover	1.75	0